

Government of West Bengal
The Regional Institute of Printing Technology
Raja S. C. Mallick Road, Jadavpur, Kolkata - 700032

Ref No.5 – QTN/RIPT/2021-22/79

Date: 13/11/2021

TENDER NOTICE

You are hereby requested to submit your **lowest rate including all Tax** in a SEALED COVER of the listed GOODS/ARTICLES/SERVICES based on specific TERMS & CONDITIONS which are mentioned in an enclosed sheet. You must provide the TENDER NOTICE No. and DATE on the quotation cover. The bidders must maintain the following format while participating the tender.

| | | |
|------------------------------------|------------|-----------------|
| Last Date of quotation submission: | 30-11-2021 | Time: 2.00 P.M. |
| Date of opening – | 30-11-2021 | |

| Sl.No. | PARTICULARS | QUANTITY | RATE | AMOUNT | | | |
|---|----------------------------|--|--|-------------|---|--|--|
| Multimedia Lab (Room No. 403) New building | 30 | Computer no. | | | | | |
| | | No. 4 Dell | Motherboard Battery change is required | | | | |
| | | No. 5 Dell | Motherboard Battery change is required | | | | |
| | | No. 7 Dell | Motherboard Battery change is required | | | | |
| | | No. 8 Dell | Motherboard Battery change is required | | | | |
| | | No. 9 Dell | Motherboard Battery change is required | | | | |
| | | No. 10 Dell | Motherboard Battery change is required | | | | |
| | | No. 11 Dell | Motherboard Battery change is required | | | | |
| | | No. 12 ACER | Motherboard Battery change is required/SMPS problem | | | | |
| | | No. 13Dell | Motherboard Battery change is required | | | | |
| | | No. 14Dell | Motherboard Battery change is required/software problem | | | | |
| | | No. 15 Dell | Motherboard Battery change is required/software problem | | | | |
| | | No. 16 Dell | Motherboard Battery change is required/software problem | | | | |
| | | No. 17 Dell | Motherboard Battery change is required/ | | | | |
| | | No. 18 Dell | Motherboard Battery change is required/ | | | | |
| | | No. 20 ACER | Motherboard Battery change is required/ | | | | |
| | | No. 21 ACER | Motherboard Battery change is required/ | | | | |
| | | No. 22 ACER | Motherboard Battery change is required/software problem | | | | |
| | | No. 23 Dell | Motherboard Battery change is required | | | | |
| | | No. 24 ACER | Motherboard Battery change is required/software problem/HDD defect | | | | |
| | | No. 25 ACER | Motherboard Battery change is required. | | | | |
| | | No. 26 ACER | Motherboard Battery change is required. | | | | |
| | | No. 27 ACER | Motherboard Battery change is required/software problem | | | | |
| | | No. 28 Dell | Motherboard Battery change is required/software problem | | | | |
| | | No. 29 Dell | Motherboard Battery change is required/software problem | | | | |
| | | No. 30 Dell | Motherboard Battery change is required/software problem | | | | |
| | | No. 31 ACER | Motherboard Battery change is required | | | | |
| | | No. 32 ACER | Motherboard Battery change is required | | | | |
| | | No. 33 ACER | Motherboard Battery change is required/software problem | | | | |
| | | No. 34 Dell | Motherboard Battery change is required/monitor problem | | | | |
| | | No. 35 Dell | Motherboard Battery change is required | | | | |
| | | 1 | HP Scanjet G4050 Scanner | | Not working | | |
| | | Multimedia Lab (Room No. 401) New building | 31 | 28 | UPS (Numeric 1000 Digital 2 batteries per UPS) | battery Defect (NEW BATTERIES INSTALLED) | Rate should be quoted with service charge. |
| | | | | 1 | UPS (Numeric 1000 Digital 2 batteries per UPS) | battery Defect (NEW BATTERIES INSTALLED) | Rate should be quoted with service charge. |
| | | | | 1 | APC 600 UPS | Not working | Rate should be quoted with service charge. |
| | | | | 1 | APC 600 UPS | Not working | Rate should be quoted with service charge. |
| Room No. B/2/N 405 (New building) | 1 | HP Scanjet G4050 | Not working | | | | |
| Room No. B/2/N 405 (New building) | 1 | Samsung printer ML1676 P | Not working | | | | |
| Multimedia Lab (Room No. B/2/N 101) Ground floor New building | 1 | Computer (Pascal) | Motherboard Battery change is required/software problem | | | | |
| Multimedia Lab (Room No. B/2/N 101) Ground floor New building | 1 | Computer (Pascal) | Motherboard Battery change is required/software problem | | | | |
| Multimedia Lab (Room No. B/2/N 101) Ground floor New building | 1 | Xerox phaser 3121 Printer | Not working | | | | |
| Multimedia Lab (Room No. B/2/N 101) Ground floor New building | 1 | HP Scanjet G 4050 Scanner | Not working | | | | |
| Language Lab (Room No. B/2/N 101) ground floor, New building | 13 | Computer 1 | Software problem/battery defect | | | | |
| | | Computer2 | SMPS/Ram/HDD defect | | | | |
| | | Computer3 | SMPS/Battery defect | | | | |
| | | Computer 4 | SMPS/Battery defect | | | | |
| | | Computer 5 | SMPS/MB defect | | | | |
| | | Computer 6 | SMPS/MB defect | | | | |
| | | Computer 8 | Motherboard Battery change is required | | | | |
| | | Computer 9 | Motherboard Battery change is required | | | | |
| | | Computer 10 | Motherboard Battery change is required | | | | |
| | | Computer 11 | Motherboard Battery change is required/Graphicscard defect | | | | |
| | | Computer 12 | Software problem | | | | |
| | | Computer 13 | Motherboard defect | | | | |
| | | Language Lab (Room No. B/2/N 101) ground floor, New building | 12 | APC 600 UPS | Logic board/Battery defect | | |
| Microtek UPS | Battery defect | | | | | | |
| Microtek UPS | Battery defect | | | | | | |
| Microtek UPS | Battery defect | | | | | | |
| APC 500 UPS | Battery defect | | | | | | |
| APC 650 UPS | Logic board/Battery defect | | | | | | |
| APC 500 UPS | Battery defect | | | | | | |
| HCL 600 UPS | Logic board/Battery defect | | | | | | |
| APC 500 UPS | Logic board/Battery defect | | | | | | |
| APC 500 UPS | Battery defect | | | | | | |
| Microtek UPS | Battery defect | | | | | | |
| Microtek UPS | Logic board/Battery defect | | | | | | |

Contd.

Copy forwarded for information and publicity through their notice board to :

- 1 Alipore Treasury
- 2 A P C Roy Polytechnic
- 3 Womens Polytechnic
- 4 Notice board of RIPT
- 5 Store

Sd/-
Principal - in Charge
RIPT